
BendPak Technical Service Bulletin

Replacement Air Valve

BendPak TSB 98-092022


The purpose of this Technical Service Bulletin is to provide replacement instructions for the Palm Activated Push Button Air Valve (5590175). This Air Valve is utilized on a variety of BendPak Lifts and several have been found to have a defect that did not allow the Safety Locks to disengage.

Replacing the Air Valve

Retrieve and discard the Air Valve (5590175) delivered with the Lift.

To install the replacement Air Valve:

Using the replacement Valve included with this Service Bulletin, follow the installation instructions as detailed in the Installation Manual.



Technical support and service is available from your dealer, on the Web, by email at support@bendpak.com, or by phone at **(800) 253-2363**, extension 196. You may also contact BendPak for parts replacement information (please have the model and serial number of your unit available) at **(800) 253-2363**, extension 191.