


## BendPak Technical Service Bulletin HD-973 Hydraulic Hose Extension

### BendPak TSB 141-072024

This TSB describes a change to the current HD-973P and HD-973PX Hydraulic Hose routing.

On all HD-973P and HD-973PX Four-Post Parking Lifts, an extension hose and nipple are added on the Hydraulic Hose routed to the Top Lift Platform. This extension will provide additional slack to allow a gentle hose bend radius extending the service life of the hydraulic hose.

The Extension Hose (5570308) will be attached to the existing Hydraulic Hose (5570871) through a JIC Nipple Fitting (5550095). Both Hydraulic Hoses will then be routed through the Flex Tube to the upper platform and then connected to the Hydraulic Cylinder as described in the Installation and Operation Manual (5900076). Refer to the figure below.



If you experience difficulties with your HD-973 Four-Post Parking Lift, technical support and service is available from your dealer, on the Web at [bendpak.com/support](http://bendpak.com/support), by email at [support@bendpak.com](mailto:support@bendpak.com), or by phone at **(800) 253-2363**, follow the prompts to reach service. Online chat is also available at [www.bendpak.com](http://www.bendpak.com)